

Adhesive Crystallization

WHAT IS ADHESIVE CRYSTALLIZATION?

Some DYMAX adhesives can exist in two liquid states, as a “liquid crystal” as well as a normal liquid. Crystallization is the transformation from the liquid to the liquid crystal state. Heat will reverse the process and restore the adhesive to its liquid state with no loss in performance. There is no effect on strength, viscosity or any other adhesives property. Crystallization is accelerated by cold storage (<50°F). Sometimes crystallization even occurs at room temperature (70°F). When dispensed, the crystallized adhesive may appear opaque, thick, or granular.

PROCEDURE FOR REVERSING CRYSTALLIZATION

Tests performed at DYMAX indicate that heating the original container of crystallized adhesive (in an oven or in a warm-water bath) to 100°F (adhesive temperature) will return the adhesive to its uncrystallized liquid state. The adhesive will reach 100°F in approximately 2 to 3 hours. Allow the adhesive to return to room temperature for consistent dispensing. As an example, an internal procedure may be as follows:

- Gently warm the original container of adhesive (or total daily consumption) to 100°F ± 5°F in oven or warm-water bath for 2.5 hours.
- Allow adhesive to cool to room temperature.
- Use in production.

Crystallization can develop in many types of packages such as syringes, cartridges and pails. It is also recommended that dispensing reservoirs, lines, valves, and needles are purged prior to prolonged periods of production shutdown (i.e., weekends, shutdowns, etc.).

NOTE: Only a very small number of adhesives are susceptible to crystallization and the likelihood of this phenomenon actually occurring is slight. Warming will restore the product to its original condition without affecting product performance. This warming procedure is repeatable and does not affect the adhesives.

© 2001-2010 DYMAX Corporation. All rights reserved. All trademarks in this guide, except where noted, are the property of, or used under license by DYMAX Corporation, U.S.A.

The data contained in this bulletin is of a general nature and is based on laboratory test conditions. DYMAX does not warrant the data contained in this bulletin. Any warranty applicable to the product, its application and use is strictly limited to that contained in DYMAX's standard Conditions of Sale. DYMAX does not assume responsibility for test or performance results obtained by users. It is the user's responsibility to determine the suitability for the product application and purposes and the suitability for use in the user's intended manufacturing apparatus and methods. The user should adopt such precautions and use guidelines as may be reasonably advisable or necessary for the protection of property and persons. Nothing in this bulletin shall act as a representation that the product use or application will not infringe a patent owned by someone other than DYMAX or act as a grant of license under any DYMAX Corporation Patent. DYMAX recommends that each user adequately test its proposed use and application before actual repetitive use, using the data contained in this bulletin as a general guide.

Lit175 11/19/2004

DYMAX Corporation
860.482.1010
info@dymax.com
www.dymax.com

DYMAX Europe GmbH
+49 (0) 611.962.7900
info_de@dymax.com
www.dymax.de

DYMAX UV Adhesives &
Equipment (Shenzhen) Co Ltd
+86.755.83485759
dymaxasia@dymax.com
www.dymax.com.cn

DYMAX Asia (Hong Kong) Ltd
+852.2460.7038
dymaxasia@dymax.com
www.dymax.com.cn

DYMAX Korea LLC
82.2.784.3434
info@dymax.kr
www.dymax.co.kr

